Figure 1. A flaked cobble with flake scars on the “dorsal” side. The red box indicates the area magnified in subsequent images.

Figure 2. The opposite side of the cobble. The blue box indicates the area magnified in subsequent images.



Figure 3. The area enclosed by the red box in Figure 1 at 100x. Note fine striae on surface called "linear indicators" suggests tool movement in two directions.



Figure 4. Close-up of the central area of Figure 3 at 200x illustrating multidirectional tool use.



Figure 5. The area in the blue box in Figure 2 at 100x showing linear indicators near the edge in perpendicular groups (yellow arrows). Note the areas of abrasive polish (red arrows).



Figure 6. The upper area of Figure 6, magnified at 200x, indicates tool use smoothed the texture of the rock surface.